

DECONTAMINATION KIT INSTRUCTIONS:

1. Locate a safe, flat terrain approximately 10' x 30' (3.m x 9.m) for the decontamination site.
 2. Remove poly drum lid.
 3. Spread plastic poly sheet over the area.
 4. Inflate containment pond, which are primary containment units.
 5. Place socks around containment pond on poly sheet as secondary containment.
 6. Remove sprayers and wash brushes from poly drum.
 7. Fill sprayers with appropriate solution based on contaminants.
- CAUTION: Use ONLY ONE SOLUTION PER SPRAYER. DO NOT mix Decon Solutions together in sprayer.
8. Place sprayers and wash brushes near primary containment units.
 9. Use wash brushes with Decon Solutions to decontaminate contaminated articles and protective clothing. WARNING: DO NOT use Decon Solutions to decontaminate human skin.
 10. Repeat Step 9 as needed.
 11. Upon final decontamination of all contaminated items, AQUALOCKIT® Polymer may be used to gel pH neutral liquids for safer handling and transportation.
 12. Dispose of all hazardous wastes and spent Decontamination Kit contents in accordance with local, state and federal regulations.

NOTE: Depending on the size and extent of the Decontamination Zone required, additional equipment may be needed. Recommended application use only as directed.

WARNING: Decon Solutions are not intended for use on human skin. Decon Solutions are recommended for use with general groups of hazardous materials. In case of a spill, obtain additional assistance from the manufacturers of the spilled materials (if available), a poison control center, medical specialists, etc. to assist in determining the best Decon Solution to use.

Specifications:

Decon Solution 1: Used as the first wash for unknown contaminants such as inorganic acids, metal processing wastes, solvents and organic materials, PBBs (Polybrominated Biphenyls), PCBs (Polychlorinated Biphenyls) and etiological materials.

Decon Solution 2: Used as the second wash for unknown contaminants and etiological materials such as heavy metals (mercury, lead, cadmium, etc.), pesticides, chlorinated phenols, dioxins, cyanides, ammonia and non-acid inorganic wastes.

Decon Solution 3: Used as the third wash for unknown contaminants such as solvents and organic compounds, PBBs, PCBs, oils and greases or unspecified wastes not suspected to be contaminated with pesticides. Can also be used as a general-purpose rinse for Decon Solutions 1 and 2.

Decon Solution 4: Used for base and caustic contaminants such as organic bases, alkali and caustic wastes.

Decon Solution 5: Used for the final wash down for Decon Solutions 1, 2, 3, and 4.

Decontamination Kit complies with D.O.T. Regulations.

THE INFORMATION PROVIDED HEREIN, IS PROVIDED "AS IS" WITH NO REPRESENTATIONS OR WARRANTIES OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. YOU ASSUME TOTAL RESPONSIBILITY AND RISK FOR YOUR USE OF THESE MATERIALS. NPS CORPORATION DOES NOT WARRANT THE QUALITY, VALIDITY, ACCURACY OR COMPLETENESS OF THE MATERIALS OR THAT THE INFORMATION CONTAINED IN SUCH MATERIALS WILL BE ERROR-FREE, OR THAT DEFECTS OR INACCURACIES WILL BE CORRECTED. NPS CORPORATION MAY MAKE CHANGES TO THE MATERIALS, OR TO THE PRODUCTS OR SPECIFICATIONS DESCRIBED THEREIN, AT ANY TIME WITHOUT NOTICE. THE MATERIALS MAY BE OUT OF DATE, AND NPS CORPORATION MAKES NO COMMITMENT TO UPDATE THE MATERIALS OR TO MAKE ANY NOTIFICATION OF CHANGES

3303 Spirit Way, Green Bay, WI 54304 • 1-800-857-8228
Fax: 1-920-983-9291 • Email: cs@npscorp.com • Web: www.npscorp.com

